RESPONSIBILITY FLOW CHART

(1) MASONRY WALL FIRE RATED

BUILDER'S RESPONSIBILITY
- **(1)**
- **(2)** WALL PENETRATION
- **(3)** STRUCTURAL ADEQUACY (SELF SUPPORTING)
- **(4)** CEILING ACCESS PANEL

FIRE DAMPER MANUFACTURER'S RESPONSIBILITY
- **(5)** FIRE DAMPER DEVICE
- **(6)** FIRE DAMPER CASING
- **(7)** MANUFACTURER'S LABEL SHOWING ORIENTATION+FRL +AIR FLOW

NOTE :-
FIRE/SMOKE DAMPER ASSEMBLY MANUFACTURED TO AS1682.1 AND INSTALLED TO AS1682.2

CHECK THAT:-
- FIRE DAMPER FRL MATCHES WALL FRL.
- FIRE DAMPER SIZE CORRESPONDS WITH WALL THICKNESS & PENETRATION SIZE

(8) SUPERVISOR'S RESPONSIBILITY

(9) FITTINGS TO RETAIN CASING

(10) DUCT BREAK AWAY CONNECTION TO AS1682.2

(11) DUCT WITH ACCESS PANEL

(12) PACKING (SEALS & EXPANDS)

DUCTWORK INSTALLER'S RESPONSIBILITY

(13)

(14) INSTALLER'S LABEL

FIRE DAMPER INSTALLER LABEL

CHECK THAT THE:-
- DAMPER FULLY OPENS
- FLANGES ARE TIGHT AGAINST WALL
- DAMPER IS RIGHT WAY UP
- AIR FLOW DIRECTION IS OK.
- FLANGE WIDTH IS OK.
- DAMPER IS CLEAR OF RUBBISH
- PAPER WORK IS OK.

PLASTER BOARD WALL FIRE RATED

(1)
(2) STRUCTURAL ADEQUACY (SELF SUPPORTING)
(3) WALL PENETRATION
(4) CEILING ACCESS PANEL

BUILDER'S RESPONSIBILITY